
CASHUP
BANKSON
STEPTOE
ABANDONED DEC 17, 1980
NON OP JAN 1, 1981
ABANDONED 12-17-80
NON OP 1-1-81
Scale 1 inch = 400 Ft.
R/W Map is 1605-22
G53-6
G53-7
Whitman County