


B ~~A~~

# TESTING THE TYPE K D.C. INTERLOCKING RELAYS INTERLOCKING DOGS



CORRECT ADJUSTMENT WITH BOTH RELAY ARMATURES PICKED UP  
CLEARANCE AT a-a SHOULD BE  $\frac{1}{64}$ " TO  $\frac{1}{32}$ " (.020")  
CLEARANCE AT b SHOULD BE ABOUT  $\frac{3}{64}$ " (.040)  
DOGS SHOULD BE RESTING ON LUGS c-c  
MAKE SEVERAL OPERATING TESTS BY SHUNTING TRACK CIRCUITS  
IN THE SAME ORDER AS TRAIN MOVEMENTS.

G.N.R.Y.  
PLAN OF STANDARD  
OFFICE OF  
ENGINEER SIGNALS  
ST. PAUL, MINN.

Drawn by	RZ
Checked by	JST
Approved by	als
Eng'r Signals	
MAR. 10, 1953	
167-142	